

## **DIGITAL TACHOMETERS**



### **DT-6236B DIGITAL TACHOMETER**

- Non-contact measurements from 5 to 100,000 RPM
- Large 5-digit LCD display
- Store last Max/Min readings
- Proper direction of the light beam is indicated by a panel light
- Auto ranging function
- Fast sampling time
- Complete with (23") reflective tape(only 1/4"square needed for measurements), four 1.5 Volt AA batteries and case

#### **SPECIFICATIONS:**

	Measurement	Resolution
Contact Tach	-5 to 19,999 RPM	0.1RPM(0.5 to 999,9 RPM)
		1RPM(over 1,000 RPM)
Surface speed(mi/min)	-0.05 to 1,999,9m/min	0.01m/min(0.05 to 99,99m/min)
		0.1m/min(over 100m/min)
Surface speed(ft/min)	-0.2 to 6,560 ft/min	0.1 ft/min(0.1 to 999,9 ft/min)
		1 ft/min(over 1,000 ft/min)



### **DT-6234B DIGITAL TACHOMETER**

- Easy to get high resolution
- Fast sampling time: 1 to 2 second
- Auto ranging with 0.05%RPM accuracy of full scale
- Linear surface speeds in Ft/min or M/min
- Complete with cone, RPM sensor tip, surface speed wheel, four
- 1.5 Volt AA batteries and carrying case

#### **SPECIFICATIONS:**

Test range	2.5 to 99,999 RPM(r/min)
Resolution	0.1 RPM(2.5 to 999,99RPM)1RPM(over 1000RPM)
Total test range	1~99999